

Ideal Products, Inc.

126 Capital Ct
Nicholasville, KY 40356
Phone: 859-881-8665
Toll Free: 866-931-4363
Fax: 859-881-8880



August 15, 2024

This letter is to inform our customers about a service that we are offering.

Any PAN disrupters that are 10 years and older, we offer a full inspection of the barrel and breech.

We will inspect the barrel for bulges, damaged threads, cracks or any other damage. If we can repair any damage, we will do so. If there is any damage or concerns, we will notify the owner of the concern and discuss any options, including possible replacement.

We will also inspect the breech for any damage to the threads and inspect all internal parts. This will include bad threads, damaged parts, bent firing pin, etc. We will replace all parts that need to be replaced and test fire the breech after the full inspection and look for any issues.

We offer this service for \$175.00. This will include return Continental US shipping.

THIS IS NOT A RECALL. This is only a service for disrupters at 10 years of service or any disrupters that have had an issue or consistent misfires.

As of this date, 08-15-2024, disrupters with serial numbers before 5000 or BC0600. Any T3 disrupters that you would like to have inspected can also take advantage of the \$175.00 inspection.

Scott Johns
President

scott@idealproductsinc.net or josh@idealproductsinc.net
www.idealproductsinc.net